# Trough Automation PCB - Introduction & first steps

## Quick Info

- Wifi 2,4Ghz
- Tasmota
- DC Input 4.75V - 36V
- Nano Fuse (1A - 5A)
- Switching High Current / Voltage DC Devices (example: Valves, Motors, ...)
- Solder Pads for OneWire device (example: DS18B20 Temperature Sensor)
- Solder Pads for Button / Switch
- Space for additional modifications

From:
https://wiki.eolab.de/ - **HSRW EOLab Wiki**

Permanent link:
**https://wiki.eolab.de/doku.php?id=eolab:ioa:trough_automation:start&rev=1645178187**

Last update: **2022/02/18 10:56**