


# Trough Automation PCB

## Quick Info

- Wifi 2,4Ghz
- Tasmota
- DC Input 4.75V - 36V
- Nano Fuse (1A - 5A)
- Switching High Current / Voltage DC Devices (example: Valves, Motors, ...)
- Solder Pads for OneWire device (example: DS18B20 Temperature Sensor)
- Solder Pads for Button / Switch
- Space for additional modifications



From:  
<https://wiki.eolab.de/> - HSRW EOLab Wiki

Permanent link:  
[https://wiki.eolab.de/doku.php?id=eolab:ioa:trough\\_automation:start&rev=1645179196](https://wiki.eolab.de/doku.php?id=eolab:ioa:trough_automation:start&rev=1645179196)

Last update: **2022/02/18 11:13**

